

RB GT2-900R74410

ADHS

ILLUSTRATED PARTS LIST

CSP-900IPL-4

FILE COPY

JUL-26-1995 15:47

COM'L FIELD SERVICE




Figure 6. T603 Drive Shaft Nut Torque Socket - Field Fabricated

91-10-00

Page 7
Revision 2

P.08